

INSTALLATION TECHNICIAN AIR CONDITIONING – VENTILATION

Warsaw, January 22, 2016

PRICE LIST OF BASIC SERVICES

Type of service	Price net (netto)
Split	
installation of the air conditioner up to 5 kW	300,00 €
installation of the air conditioner above 5kW	375,00 €
service inspection of the air conditioner	50,00 €
Multisplit	
installation of the air conditioner 2 + 1 (2 units ext. - 1 outdoor unit.)	447,50 €
installation of the air conditioner 3 + 1 (3 units ext. - 1 outdoor unit.)	525,00 €
installation of the air conditioner 4 + 1 (4 units ext. - 1 outdoor unit.)	672,50 €
installation of the air conditioner indoor units above 4	<i>to be confirmed</i>
service inspection of the air conditioner 2 + 1	67,50 €
service inspection of the air conditioner 3 + 1	85,00 €
service inspection of the air conditioner 4 + 1	117,50 €
service inspection of the air conditioner indoor units above 4	<i>to be confirmed</i>

The above prices include the installation of split air conditioners and review and multisplit wall, ceiling, and floor.
In the case of air-conditioning duct and cassette price will be determined individually for each installation.

Installation of the base consists of the following elements:

- make the necessary holes to install.
- installation of the indoor unit (evaporator) in the indicated place
- installation of the outdoor unit (condenser) in place on the wall sentenced to 5 m in height
- brackets for outdoor unit (condenser)
- wiring and installation between indoor and outdoor unit up to 5 m (installation does not include mounting trays)
- Connect the air conditioner to an existing electrical wiring to 2 m (installation does not include trays assembly)
- installation of a gravity drain condensate from the indoor unit to 3m
- installation freon leak test
- pumping atmospheric air (vacuum) with the installation of freon
- launch and test automation and validation of devices
- instruction manual

INSTALLATION TECHNICIAN AIR CONDITIONING – VENTILATION

Warsaw, January 22, 2016

ADDITIONAL SERVICES PRICE LIST

Type of service	Price net (netto)
additional meter installation freon to 5 kW	12,50 €
additional meter installation freon exceeding 5 kW	19,75 €
the trough assembly (depending on the cross section)	6,50 €/mb.
additional drilling through the wall to 40 cm - diamond drill	18,75 €
drilling passage in the wall above the 40 cm - diamond drill	0,50 €/cm
fixing the condenser with aerial platform	50,00 €/h
chiselling in brick	7,50 €/m
chiselling in concrete	to be confirmed
switching power supply	9,75 €/m
complement the refrigerant	24,00 €/kg
PVC gravity condensate drain	5,00 €/m
drain pump installation	112,50 €
traveling to clients	0,00 €

WARRANTY

The warranty for the service is 36 months. This warranty is conditioned air service at least twice a year by an authorized service center. Maintenance inspections are necessary to ensure the proper fail-safe operation of the air conditioner, the user is required to carry out at least two technical inspections. If the air conditioner is under warranty, in the absence of mandatory technical inspections performing user loses all rights under the warranty.

The maintenance services include:

- fumigation units
- cleaning the filters of the indoor unit
- cleaning the evaporator and condenser fins
- Check refrigerant fill level, and complement, if that is desired
- Check the tightness of connections Freon systems
- Check the tightness of the drain
- Check the wires and insulation for mechanical damage
- checking the operation of the control devices